

**Village of Combined Locks
Grease Trap Inspections Summary Report
April 30, 2015**

FOG Control Program Update

In cooperation with HOVMSD Staff, we have put together a draft set of procedures to investigate non-commercial dischargers that are suspected of discharging FOG to the sanitary sewer. These dischargers could include facilities which already have grease traps or those that may be required to add a grease trap. A copy of the draft is included with this mailing.

The proposed procedures will be discussed at the June 9 Commission meeting. Of interest is the provision asking for periodic reporting from the Communities in regard to the results of their sanitary sewer maintenance and inspection programs. Each Community's input on the provision is encouraged.

Summary of Site Visits

All sites requiring a grease trap have now completed their installations and have been assigned cleaning schedules, per the attached table.

Reminder Letters

No reminder letters for are required for June.

Site Visits

No site visits are scheduled for June.

Periodic Grease Trap & Lateral Inspections:

As part of the Village's continues maintenance and inspection of the sanitary sewer system, we recommend that the downstream manhole from the following businesses be periodically inspected.

The Lox Club
Rico's Family Restaurant (Former Kim's Place)
Jerry Kamp's Bar
Mill Town Still and Grill