

# **Village of Combined Locks Grease Trap Inspections Summary Report July 31, 2015**

## **FOG Control Program Update**

Signage has been printed for placement in the community centers and park shelters asking users not to place fats, oil or grease down the sink drains. We will meet with the appropriate persons from each community to ask that these be placed near any sinks in the public areas. If additional signs are available, we will hand them out to other non-residential users.

Each community should have received a final copy of the “FOG Control Program Procedures for Sanitary Sewer Televising and Sampling.” The guide will be used when areas requiring additional investigation are identified by maintenance crews. Of note on the guidelines is the request that each community present an opinion as to how intrusive any private lateral inspection may be. Example may include: “Not to extend past the main sewer line”, “To the first bend in the lateral”, “To the terrace or sidewalk” or “All the way to the house.”

Also, the guidelines add a reporting requirement regarding observations of manhole and piping conditions (in regards to the presence of grease) noted during routine maintenance or manhole inspections. A summary report will be required as part of the CMOM submittals to HOVMSD.

## **Reminder Letters**

Jansen School  
Jerry Kamp’s Bar  
Mill Town Still and Grill  
St. Paul’s Church

## **Site Visits**

No site visits are scheduled for August.

**Periodic Grease Trap & Lateral Inspections:**

As part of the Village's continues maintenance and inspection of the sanitary sewer system, we recommend that the downstream manhole from the following businesses be periodically inspected.

The Lox Club  
Rico's Family Restaurant (Former Kim's Place)  
Jerry Kamp's Bar  
Mill Town Still and Grill