

# FOG Control Program Procedures Sanitary Sewer Televising and Sampling

1. Work with the street department or other municipal employees from each community to identify sub-basins in which grease is noted in manholes and/or piping or a heavy sheen is noted on the wastewater surface.  
**Summary reports from each Community shall be submitted every 6 months, documenting the investigation activities and findings of any manhole and/or sewer inspection work performed during the reporting period.**
2. Identify potential FOG dischargers within the area noted.
3. Obtain drawings of sanitary sewer with lateral locations.
4. If possible, televise sanitary sewer from manhole immediately downstream of potential source(s) of FOG and to manhole directly upstream of potential FOG source(s). Televise during times in which peak FOG discharges may be present. (Restaurants, during busiest hours of service, food processing/manufacturing, during normal production times.)
5. Collect grab sample sets from the closest upstream and downstream manholes to be analyzed for FOG. Each set of samples should be collected from a consistent same depth within the flow stream and at the same time.
6. Identify the location and document the condition of each lateral found during televising. Confirm lateral locations with available drawings.
7. To the extent permissible, televise any laterals that appear to contain residual FOG or are discharging wastewater that appears to have a surface sheen. **Each Community shall submit their guidelines as to how intrusive the televising activities may be, in regard to private laterals.**
8. If the visual or analytical investigations determine that a business is discharging FOG to the sanitary sewer, they will be added to the FOG Control Program.



1380 Earl St  
 Menasha, WI 54952  
 920-734-4707

**Quote**

Date	Estimate
3/25/2020	183

Name / Address
Heart of the Valley MSD 801 Thilmany Rd Kaukauna, WI 54130

Service Point

P.O. No.	Project

Description	Extension
Televise as requested on an as needed basis would be charged at \$265.00/hr. with a 2 hour minimum -- normally it would take approx. 2 hours to do this type of televising. Also, be aware that we do have lateral launching ability - we can run a camera from the city main up a lateral to inspect.	0.00
Sales Tax	0.00

<b>Total</b>	<b>\$0.00</b>
--------------	---------------

Please notify Speedy Clean within 30 days if the quotation is accepted and the above prices will be honored.

Cured in Place Pipe repairs come with a 5 year warranty on parts and installation.

If prevailing wages apply - this quote will be adjusted accordingly.

Due to the unique nature of the tasks and the unknown pipe conditions, completion of the work may not be possible. Speedy Clean will make every reasonable effort to perform the work described.

Signature \_\_\_\_\_



3600 Kewaunee Road  
 Green Bay, WI 54311  
 Phone: (920)863-3663  
 Fax: (920)863-3662

# Quotation

Quote Number  
13030

Quote Date  
Mar 19, 2020

**Quoted to:**

HEART OF THE VALLEY METRO.  
 801 Thilmany Road  
 Kaukauna, WI 54130

Quote Good Thru	Payment Terms	Sales Rep
4/18/20	Net 30 Days	BH

Description	Unit of Measure	Quantity	Unit Price	Extension
T&M RATES FOR TV INSPECTION TO LOCATE SOURCES OF GREASE	.			
MOBILIZATION/DEMobilIZATION - TV UNIT AND CREW	HOURL	1.00	155.000	155.00
TV INSPECTION UNIT AND CREW	HOURL	1.00	215.000	215.00
MAJOR TRAFFIC CONTROL WOULD BE CHARGED ACCORDINGLY	.			

Please notify Great Lakes within 30 days if the quotation is accepted and the above prices will be honored. This acknowledgment will enable us to schedule your work more efficiently. If prevailing wages apply - this quote will be adjusted accordingly. Bond fee and/or additional insurance requirements are not included in the quote amount. If applicable, add the amount(s) to this quote.

<b>Subtotal</b>	370.00
<b>Sales Tax</b>	
<b>Total</b>	370.00