

Operations Update

Plant operations and treatment were really good during the month of July with the exception of July 13th and 14th when we had a blending event from 10:15 pm to 2:11 am. Disc filters ran continuously through the month of June with no chemical addition when Veolia wasn't onsite.

Maintenance Update

Atad Blower #2 VFD: The VFD on Blower #2 was rebuilt and installed in May 2024. It would not turn back on after being taken down for maintenance in July. Werner and Rockwell will be exchanging our unit with another one under warranty. If Rockwell voids the warranty for any reason we could be invoiced for \$16,645.

Biostyr Blower #1: Biostyr Blower #1 was leaking oil out of the weep hole on the drive end of the blower. The blower was taken out of service and replaced with the spare blower that we just got back from Aerzen. This blower was sent into Aerzen to be inspected for rebuild or full replacement. Aerzen has not come back with a report yet.

Biostyr Blower #4: Biostyr Blower #4 was leaking oil out of the seals on the drive end of the blower and turning the oil black and had metal flakes in it. The blower was taken out of service and replaced with an exchange unit from Aerzen for a price of \$8,500. We exchanged this unit so we could avoid down time of a cell in biostyr.

Biostyr Blower #5: The fire investigation of biostyr blower #7 brought forward a belt pulley issue with blower #5 that we are addressing by replacing both v-belt pulleys and the belts at a cost of \$1,818. We also received a quote for a full preventative maintenance inspection on all the biostyr blowers by Aerzen for \$5,642.

Dustin Jerabek
Director of Operations & Maintenance