

Village of Combined Locks Grease Trap Inspections Summary Report June 30, 2015

FOG Control Program Update

We have prepared some samples of informational signs that can be placed in park shelters asking users not to put grease down the drains. The content and placement of the signs will be discussed at the July Commission meeting.

At the June Commission meeting, the guidelines for televising sanitary sewer lines and laterals were approved. Within the guidelines are requirements for submitting a summary report, by each community, of their manhole and sewer inspection findings every 6 months, as they relate to the observation and removal of grease in the sewer and manholes.

Each Community is asked to define the limits in which sewer televising may take place, in regards to televising private laterals from the main sewer and without the property owner's permission.

Reminder Letters

No reminder letters for are required for July.

Site Visits

No site visits are scheduled for July.

Periodic Grease Trap & Lateral Inspections:

As part of the Village's continues maintenance and inspection of the sanitary sewer system, we recommend that the downstream manhole from the following businesses be periodically inspected.

The Lox Club
Rico's Family Restaurant (Former Kim's Place)
Jerry Kamp's Bar
Mill Town Still and Grill