

# **Village of Little Chute Grease Trap Inspections Summary Report December 31, 2015**

## **Summary of Site Visits & Correspondence**

**Village Lanes:** We personally stopped in to see the owner on 12/8 and 12/31. She was not available and did not return our calls. We also called several times over the course of the month and received no return calls. Previously, she indicated that she had retained Reader Plumbing to complete the grease trap installation. The number she gave us for the plumber goes unanswered.

If we do not hear from her by January 4, 2015, we will send her a letter requesting her presence at the February Commission meeting to explain her unwillingness to install the grease trap. If that does not achieve the desired results, we will recommend citing them for non-compliance.

**Jack's or Better:** On December 18, 2015, we met with the new owner of Jack's or Better. They do have a grease trap and a contractor has been retained to do their cleanings.

**Hawk's Nest:** On December 31, 2015, we met with the manager of the Hawk's Nest and explained the requirements of the FOG Program. The facility does have a grease trap already installed.

### **Sites Requiring Grease Traps:**

Village Lanes (Status Unknown)

### **Reminder Letters to Send:**

El Jaripeo  
Simon's Specialty Cheese  
Taste of the Windy City

### **Site Visits**

Burger King  
Landreman's Restaurant