## **Operations Update**

<u>Plant Operations</u> – Plant operations and treatment were good during the month of October.

## **Maintenance Update**

Storage Tank Valve – After about 30 years of service a 16-inch underground valve that feeds the pumps in the pump building from tank number one failed; the valve would not open. Was able to order a 16-inch plug valve, plus receive the valve in about a week. Due to the urgency, time, & location of valve and August Winters being able to replace it when the new one came, a quote was received from them.

August Winters – Time and materials not to exceed \$15,119 Valve - \$7,850

<u>Solids Building Lighting Transformer</u> – A 480-volt to 277-volt lighting transformer failed in the solids building at the end of September. All lighting was out in the building for several days. Sargent Electric was already on site and located a transformer and was able to get it here in a few days and replace the failed one. Sargent Electric had supplied temporary lighting in areas where lighting was needed.

Biostyr Blower - No blower issues this past month.

Kevin Skogman
Director of Operations & Maintenance